AlephObjects.com

3D Printers, Parts, and Plastics

+1-970-377-1111 shop@alephobjects.com 626 West 66th Street Loveland, Colorado 80538



Service Bulletin

Affected product: Budaschnozzle Hot Ends, version 2.0c

Effective date: December 22 2014

Service issue: When printing with PLA users may see visible plastic on

the threading of the hot end.

Indication:

Some users have reported leaking on the threading of the Budaschnozzle 2.0c hot end when printing with PLA. Leaking may be occurring from the PEEK insulator, from above the heater block or from the nozzle.

Corrective Action:

Add extra PTFE tape on the threaded extension after cleaning the threads- typically a length of 100mm is recommended. Try one of the three solutions at:

https://www.lulzbot.com/support/budaschnozzle-20-pla-solution or submit the hot end for an exchange by contacting the Support team at Support@LulzBot.com.

